

### MISSOURI DEPARTMENT OF HEALTH STATE PUBLIC HEALTH LABORATORY

# **DATAMASTER MAINTENANCE REPORT**

RECEIVED DHS 3 Broath Akotod Program By Carol Day at 1:47 pm, Sep 02, 2009

Complete this report in duplicate at the time of the regular monthly preventive maintenance check, and whenever instrument is repaired. Send copy to Department of Health; retain original in department file.				
DATAMASTER SN 204108			TE OF INSPECTION	
LOCATION OF INSTRUMENT (STREET AND CITY)			IE OF INSPECTION	
Ralls Co. Sheriffs Dept., 301 Ralls St., New London, MO 634			1757	
CHECKLIST: Place a check (✓) to the left of each item if found to be satisfactory or if operating within established limits. (Write in observed values where determined.) Unchecked items must be corrected before using instrument.				
☑ DIAGNOSTIC CHECK (PRINTOUT ATTACHED)				
☑ COMPUTER	☑ DETECTOR			
☑ PROGRAM	☑ FILTERS			
☑ HEATERS SAMPLE CHAMBER°C	Quartz standard			
☑ FLOW DETECTOR	☑ CALIBRATION			
☑ PUMP HIGH SPEED	PRINTER			
☑ INDICATOR LIGHTS				
☑ TIME AND DATE				
SIMULATOR TEMPERATURE (34 °C ± 0.2°C)				
☑ CALIBRATION CHECK -				
Run three tests using a standard solution. All three tests				
spread of .005 or less. Check the box corresponding to the standard solution being used. (PRINTOUT ATTACHED) (USE RECIRCULATION PUMP)				
🗹 0.100% STANDARD - MUST READ BETWEEN 0.095% and 0.105% INCLUSIVE				
☐ 0.040% STANDARD - MUST READ BETWEEN 0.038% and 0.042% INCLUSIVE  (ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT)				
	3.3	ST3 📂	.098	
PERFORM R.F.I. TEST (PRINTOUT ATTACHED)				
☑ NUMBER OF REFUSALS, SINCE LAST MAINTENANCE REPORT, AND NUMBER OF BREATH TESTS IN EACH RANGE AS				
FOLLOWS: (DO NOT INCLUDE SIMULATOR TESTS)				
REFUSALS / (004) / (.0509) /	(.1014) (.1519	9) <i>C</i>	) (Over .19) <i>O</i>	
List any new parts and describe any alteration or modification that was made to restore the instrument to operate satisfactorily				
and within established limits (use other side if necessary)				
Instrument meets Dept. of Health specs., Guth Labs., .10 solution, lot no.08340, exp. 10-15-09				
INSPECTING OFFICER SIGNATURE	PRINT NAME			
B. C. Malli	B, C, Griffin			
type II permit number/expiration date 920080 / 04-22-2011	TELEPHONE NUMBER (660) 385-2132			



# CERTIFICATE OF ANALYSIS

Certified Alcohol Reference Solution for Simulator

Random Samples of Lot Number 08340 of Alcohol Reference Solution for Simulator were analyzed by gas chromatography and found to contain 0.1211 percent (w/vol) ethyl alcohol. The expiration date for this lot number is October 15, 2009 at 11:59 PM.

When used in a calibrated Simulator, operating at 34°C +/- .2°C, this solution will give a breath alcohol. analysis instrument reading of 0.10 percent BAC.

The alcoh: and water used in this solution were free of test interfering substances.

Ted L. Pauley, President GUTH LABORATORIES, INC.

### Face This Side Down - This Edge In First

# **BAC DataMaster**Evidence Ticket

MISSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL NUMBER 204108 08/30/09

TESTING OFFICER:
GRIFFIN/BRANDON/C
OFFICER I.D.: 0429
PERMIT NUMBER: 920080
EXPIRATION DATE: 04/22/11
MISCELLANEOUS DATA:

### --- SUPERVISOR MODE ---

BLANK TEST INTERMAL STANDARD EXTERNAL STANDARD BLANK TEST EXTERNAL STANDARD BLANK TEST EXTERNAL STANDARD BLANK TEST EXTERNAL STANDARD BLANK TEST	VERIFIED .096 .080 .098 .000 .008	18:02 18:02 18:03 18:04 18:05 18:05
--	--	--

N = 3 SIM, = .1 AVG. = .0973

# Face This Side Down - This Edge In First

# **BAC DataMaster**Evidence Ticket

MISSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL MUMBER 204108 08/30/09 17:57

--- DIAGNOSTIC CHECK ---

COMPUTERS UKHY PROGRAM (64-87-2009): OKAY HEATERS SAMPLE CHAMBER: 490 FLOW DETECTOR: OKEY PUMP HIGH SPEEDS UKAY DETECTORS OKAY FILTERS: UKAY QUARTZ STANDARD: OKRY CHLIBRATION: UKAY


PRINTER TEST

"#\$%\$^()#+.-./@123456789::(<)?@ABCDEFU HIJKLMNOPGRSTUVWXY2[\]^|\*abcdetahi.ik]mno sarstuvwxuz(|)+"

Operator Signature

Printed on recycled paper with agri-based ink

CMSU 2208-02



# **BAC DataMaster**Evidence Ticket

MISSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL NUMBER 204108 08/30/09

ARREST TIME: 17:00 SUBJECT MAME: TEST DOB: 01/01/79 SEX: H STATE/D.L.: MO/1234567890 ARRESTIMG OFFICER: GRIFFIN/BRANDON/C OFFICER 1.D.: 9429 TESTING OFFICER: BRIFFIN/BRANDON/C OFFICER I.D.: 0429 PERMIT HUMBER: 920090 EXFIRATION DATE: 01/01/70 MISCELLANEOUS DATA: R.F.I. TEST

--- BREATH AMALYSIS ---

BLANK TEST INTERNAL STANDARD RADIO INTERFERENCE . 986

 $\tfrac{1}{2}\{\tfrac{n}{2}\{\tfrac{n}{n},\tfrac{1}{2},\tfrac{1}{2}$ 

VERIFIED 18:11

Operator Signature

Printed on recycled paper with agri-based inks

CMSU 2208-02

# State of Missouri DEPARTMENT OF HEALTH



)

# PERMIT TYPE II



# **BRANDON GRIFFIN**

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field repairs, and operate the following breath analyzer(s):

# calibrate, perform field repairs, and operate the following breath analyzer(s): DATAMASTER for the determination of the alcoholic content of blood from a sample of expired (alveolar) air. Issued under the provisions of sections 577.020 through 577.041, RSMo 1986. Date 04/22/09 Number 920080 Number 04/22/2011 Expires Director of State Public Health Laboratory Margart 1. Danuelly Director, Department of Health Lab. 4 (R7-88)